

URL: http://cxc.harvard.edu/ciao3.4/dictionary/streak.html Last modified: 15 December 2008

Streak Events

There is a flaw in the serial readout of the ACIS chips, causing a significant amount of charge to be randomly deposited along pixel rows as they are read out. Chip S4 (ccd_id=8) is most affected by this problem.

On account of the serial readout problem, the event file shows a variable pattern of linear streaks. These events may be flagged in or removed from the file with the <u>destreak</u> tool, as shown in the <u>Destreak the ACIS-S4 Chip</u> thread.

Technical details on the correction are available in the destreak memo.

The Chandra X-Ray Center (CXC) is operated for NASA by the Smithsonian Astrophysical Observatory. 60 Garden Street, Cambridge, MA 02138 USA. Smithsonian Institution, Copyright © 1998-2008. All rights reserved.

URL: <u>http://cxc.harvard.edu/ciao3.4/dictionary/streak.html</u> Last modified: 15 December 2008